



# OTHELLO

HOTEL & CONTRACT \_Contract \_ Hôtellerie \_ Hotel

## Finiture \_ Finishes \_ Finitions \_ Afwerkingen

**ABS**

ABS

ABS

ABS



**.29**








# OTHELLO

## 532621

### Asciugacapelli compatto a parete 1400 Watt

Wall hairdryer 1400 W / Sèche-cheveux électrique mural 1400 W - Wand-Haartrockner 1400 W



<b>cod. 532621</b>	 <b>0,900</b>	 <b>4,586</b>	 <b>1</b>	<b>ABS</b> ABS ABS ABS
<b>EAN 8005049002345</b>	<b>0,900</b>	<b>4,586</b>	<b>1</b>	

Peso e volume lordo / Gross weight and volume / Poids et volume brut / Bruttogewicht und Volumen



IP20  
IP20  
IP20  
IP20



Marchatura CE  
CE mark  
Label CE  
CE Kennzeichen



Marchio Classe II  
CLASS II mark  
Label CLASSE II  
KLASSE II Kennzeichnung

#### PULIZIA e MANUTENZIONE

Pulire con un sapone neutro, applicare con un panno umido, strofinare leggermente, lasciar agire brevemente e quindi sciacquare con acqua. Infine lucidare con un panno morbido e asciutto. Per macchie di calcare pulire con una soluzione di acqua (80%) e aceto bianco (20%), per un'azione igienizzante aggiungere alla soluzione del bicarbonato di sodio. Asciugare sempre la superficie in modo da evitare le macchie derivanti dall'acqua.

Avvertenze: La resistenza alla corrosione al nichel-cromo si riduce sotto l'azione di acidi e composti alogenati (cloruri, bromuri, ioduri). Non utilizzare mai soluzioni a base di cloro (candeggina), detersivi o spugne abrasive. Evitare la ruggine causata da materiali esterni (ad es. paglietta di acciaio ecc.).

#### CARE and MAINTENANCE

Clean with a mild soap, apply with a damp cloth, rub lightly, leave it briefly and then rinse with water. Finally polish with a soft, dry cloth. To remove the limestone stains, clean with a solution of water (80%) an white vinegar (20%), to sanitize add baking soda. Always dry the surface in order to prevent stains caused by water. Warnings: The corrosion resistance of the steel is reduced by acids and halogen compounds (chlorides, bromides, iodides). Never use solutions containing chlorine (bleach), detergents or abrasive sponges. Prevent rust caused by external materials (eg. Scouring steel, etc..).